









| | | | |
|--|---|---|---|
|  M6x40 Ax12 |  ∅ 8x30 Bx12 |  Cx1 |  Ex12 |
|--|---|---|---|



1



2



3



4

| | |
|---|-------|
|  | E x12 |
|---|-------|

